



# 2006 Southeastern States Pavement Management And Design Conference

May 7-10, 2006

Panama City, Florida

# Jointed Plain Concrete Pavement, Case study

Mohamed Elfino, PhD, PE  
VDOT/ Materials Division

Shabbir Hossain, PhD, PE  
Virginia Transportation Research Council

Background

Objectives

Pavement Performance History

- Field Distress Survey
- Functional Evaluation
- Structural Evaluation

Investigation of Premature Distress

Impact of Drainage Design and  
Construction

Recommended Remedial Action

Conclusions

- Jointed Plain Concrete Pavements (JPCP)
- 15 ft joint spacing
- US 460 in Appomattox County, Virginia.
- Four-lane divided primary highway
- 2003 Traffic variable 11,000 to 14,000 ADT with 14% and 6% trucks (SU & TT).
- Built during the 1993 and 1994 construction seasons.

- 9 inches (225 mm) of doweled JPCP
- 4-inch (100 mm) Cement-Stabilized Open Graded Drainage Layer (OGDL)
- 6 inches (150 mm) of soil cement.
- Tied Concrete Shoulder
- Longitudinal Pavement Edgedrain

- Isolated areas of the 2.8-mile-long project showed signs of premature failure (since 1998), mainly mid-slab cracking, faulting, settlement, and spalling.















INCHES


1

066D

2

LUFKIN

3



- Assess the premature failure in terms of severity and frequency
- Identify the failure mechanism
- Recommend remedial action

- Field Distress Survey
  - Eastbound lanes have more distress (24% of the slabs)
  - Westbound lanes have less distress (12% of the slabs)
  - All distresses are in the travel lanes only



## Functional Evaluation

- EB 2003, IRI 87 inch/mile
- EB 2005, IRI 116 inch/mile
- WB 2003, IRI 71 inch/mile
- WB 2005, IRI 83 inch/mile

## Structural Evaluation

- FWD, Load Transfer Efficiency (LTE)
- Tested 15% of all slabs (2005)

	EB	WB
– (<50%) Low LTE	73%	vs. 36%
– (51-75%) Medium LTE	21%	vs. 28%
– (>75%) High LTE	6%	vs. 36%

- Investigated Section – 0.25 mile
- Field Cores
  - Concrete Compressive Strength (6000 psi)
  - Drainage Layer
    - Clogged in distressed area
    - Clear in undamaged area
  - Soil Cement (700 psi)
  - Subgrade – A-4 and A-5 with a soaked CBR 3.0%







Hole #2  
Approximate Exposure  
Ziploc®  
Soil Cement

AND BAGS  
CS de MARQUE  
BAGS PLÁSTICAS

Partially Eroded Soil  
Cement Core



APP. BY-PASS  
E.B.L. TRAVEL  
LANE  
Hole #3

ZIPLOC®  
BRAND BAGS  
SACS DE MARQUE  
SOLAS PLASTICAS

# Investigation of Premature Distresses

Subgrade evaluation using the  
Standard Penetration Test (SPT)

The uncorrected Blows (N) is  
between 1 and 7 very weak soil

Soil classification is A-4 & A-5



# Investigation of Premature Distress

- Video inspection of Pavement Edgedrain
- All outlets are clear
- All the longitudinal pipes are clear





















6 2'93





WILLIAMS  
CORP

CATERPILLAR

Projected (ESAL) for 30 years: 8,000,000

Reliability level (%): 95

Overall standard deviation: 0.35

28-day mean modulus of rupture for PCC:  
650 psi

28-day mean modulus of elasticity for PCC :  
3,705,000 psi


Load transfer coefficient, J factor: 3.20

Modulus of subgrade reaction (K value): 193  
psi/in

Overall drainage coefficient (Cd): 1.20

Initial serviceability: 4.5

Terminal serviceability: 2.5.



**LEGEND:**

- ① JOINTED PLAIN CONCRETE PAVEMENT (JPCP)
- ② CEMENT STABILIZED DRAINAGE LAYER
- ③ HYDRAULIC CEMENT SOIL
- ④ JPCP - VARIABLE DEPTH
- ⑤ 21 A/B - AGGREGATE
- ⑥ STANDARD UD-4

1. Remove 3ft of the concrete shoulder adjacent to the mainline.
2. The next step is digging out the native soil which caused the drainage blockage
3. Replace with a permeable aggregate course.
4. The 3 ft shoulder slab can be replaced with fresh concrete and tie bars.
5. Reseal all joints as needed
6. This recommendation would re-establish both the positive drainage and the edge support.

The lessons learned from this investigation are as follows:

1. Quality construction in accordance with proper sequence is essential for long-life concrete pavement.
2. It is important to conduct pre-paving conferences, where the designer shares the new features of his design and emphasize the critical issues to the project personnel and the contractor.
3. Quality assurance is essential in preventing premature pavement failure.
4. Concrete pavement requires stable and dry foundation in order for it to provide long life.
5. Adequate documentation of the construction activities can play an important role in detecting the failure mechanism, if any, at early stages.





1906



VDOT

From  
Mud  
to  
Mobility

100  
YEARS



2006

VIRGINIA DEPARTMENT  
OF TRANSPORTATION

Thank You,

Questions !